



JOSEPH A. FOJON

SUPERVISOR OF BUILDINGS & GROUNDS

Email: jfojon@ramsey.k12.nj.us

July 2022

TO: Faculty – Tisdale

FROM: Joseph A. Fojon 

RE: Asbestos Hazard Emergency Response Act

The Ramsey Board of Education has recently completed its required inspection of the District facilities in accordance with the Federally Mandated Asbestos Hazard Emergency Response Act (AHERA) 40 CFR 763 subpart E. The Asbestos Managed Plan for Tisdale School is available in the General Office at Tisdale School and at the BOE Building.

As part of this inspection process, we as a District are required to notify the parents, faculty, and staff annually of any pertinent changes in the District relating to asbestos containing materials. There were several changes in the condition of any of the asbestos containing materials identified in our management plan at Tisdale School. Asbestos was removed from CR 7, 8, 9, 10, 11, 12, 31, 33, 34, 35, 36, 37, and the Faculty Room. The inspection reports are on file in the General Office at Tisdale School and at the BOE Building.

All asbestos containing materials within the District are part of an ongoing Operations and Maintenance Program to keep the materials properly maintained.

Should you have any questions regarding the most recent inspection of the condition of asbestos containing materials within the District, please contact our appointed District Representative, Joseph A. Fojon, Supervisor of Buildings and Grounds at (201) 785-2300 extension 20409.

JAF:er



RAMSEY SCHOOL DISTRICT

25 N. Franklin Turnpike

Ramsey, NJ 07446

Phone: 201.785.2300 | Fax: 201.934.6623

www.ramsey.k12.nj.us

JOSEPH A. FOJON

SUPERVISOR OF BUILDINGS & GROUNDS

Email: jfojon@ramsey.k12.nj.us

July 2022

Dear Parent:

The Ramsey Board of Education has recently completed its required inspection of the District facilities in accordance with the Federally Mandated Asbestos Hazard Emergency Response Act (AHERA) 40 CFR 763 subpart E. The Asbestos Managed Plan for Tisdale School is available in the General Office at Tisdale School and at the BOE Building

As part of this inspection process, we as a District are required to notify the parents, faculty, and staff annually of any pertinent changes in the District relating to asbestos containing materials. There were several changes in the condition of any of the asbestos containing materials identified in our management plan at Tisdale School. Asbestos was removed from CR 7, 8, 9, 10, 11, 12, 31, 33, 34, 35, 36, 37, and the Faculty Room. The inspection reports are on file in the General Office at Tisdale School and at the BOE Building.

All asbestos containing materials within the District are part of an ongoing Operations and Maintenance Program to keep the materials properly maintained.

Should you have any questions regarding the most recent inspection of the condition of asbestos containing materials within the District, please contact our appointed District Representative, Joseph A. Fojon, Supervisor of Buildings and Grounds at (201) 785-2300 extension 20409.

Very truly yours,

Joseph A. Fojon

Supervisor of Buildings & Grounds

JAF:er